


# TYLER PARK MASTER PLAN

## LOUISVILLE, KENTUCKY

### EXISTING CONDITIONS

MAY 2009

SCALE: 1" = 50'



#### Existing Conditions Legend

-  Existing building
-  Existing treeline
-  Existing trees
-  Existing contours
-  Fence
-  Bollards
-  B1 6 ft wood slat bench
-  B2 6 ft perforated metal bench
-  B3 8 ft wood & pipe bench
-  FP Flag Pole
-  DF Drinking Fountain
-  CB Catch basin
-  MH Manhole
-  SAN Sanitary sewer line
-  Pedestrian Light
-  Utility Pole
-  SS Stop sign
-  NP No Parking sign
-  HC HC Parking sign

#### Existing Tree Legend

Key	Botanical Name	Common Name
AR	Acer rubrum	red maple
AS	Acer saccharum	sugar maple
ASm	Acer saccharinum	silver maple
CC	Cercis canadensis	eastern redbud
CF	Comus florida	flowering dogwood
CK	Cladrastis kentuckea	yellowwood
FA	Fraxinus americana	white ash
FP	Fraxinus pennsylvanica	green ash
JN	Juglans nigra	black walnut
LT	Liriodendron tulipifera	tuliptree
MA	Magnolia acuminata	cucumber tree
MP	Maclura pomifera	osage orange
MR	Morus rubra	mulberry
PC	Pyrus calleryana	callery pear
PS	Pinus strobus	white pine
PS	Prunus serotina	black cherry
QB	Quercus bicolor	swamp white oak
QC	Quercus coccinea	scarlet oak
QI	Quercus imbricaria	shingle oak
QN	Quercus nigra	water oak
QP	Quercus palustris	pin oak
TA	Tilia americana	American linden
UA	Ulmus americana	American elm
UP	Ulmus parvifolia	lacebark elm
UR	Ulmus rubra	slippery elm

**TREE CONDITIONS:**  
Tree conditions were evaluated on a four level system, as follows:  
(#1) Tree is in excellent condition with no apparent defects.  
(#2) Tree is in good condition but needs minor pruning or has defects.  
(#3) Tree is declining, needs major pruning, or has severe defects.  
(#4) Tree is dead or dying.